Montana Board of Oil and Gas Conservation

Environmental Assessment

Operator: Continental Resources, Inc.
Well Name/Number: Colleen 2-29H
Location: SE SE Section 29 T26N R55E
County: Richland , MT; Field (or Wildcat) W/C (Bakken Horizontal)
Thomasa, in the control of the contr
Air Quality
(possible concerns)
Long drilling time: No. 30 to 40 days drilling time.
Unusually deep drilling (high horsepower rig): No, triple derrick drilling rig to drill to
19,705'MD/9,935'TVD, single lateral horizontal Bakken Formation well.
Possible H2S gas production: Slight chance H2S gas production (Mississippian
Formations).
In/near Class I air quality area: Closest Class I air quality area is the Fort Peck Indian
Reservation.
Air quality permit for flaring/venting (if productive): Yes, DEQ air quality permit required
under 75-2-211.
Mitigation:
X Air quality permit (AQB review)
X Gas plants/pipelines available for sour gas
Special equipment/procedures requirements
Other:
Comments: No special concerns – using triple rig to drill a single lateral horizontal
Bakken Formation well test. If there are existing pipeline for gas in the area then gas
must be tied into system or if no gas gathering system nearby limited amount of gas can
be flared under Board Rule 36.22.1220.
De naied under Board Hale 50.22.1220.
Water Quality
(possible concerns)
Salt/oil based mud: Yes, freshwater and freshwater mud system on surface hole and oil
based invert drilling fluids for intermediate casing hole. Brine water will be used to drill
the horizontal lateral.
High water table: No high water table anticipated at this surface location.
Surface drainage leads to live water: No, closest drainage is Hay Coulee a tributary
drainage to East Charley Creek.
Water well contamination: No, closest water wells are about 1/2 mile away a shallow.
Surface hole will be drilled with freshwater and freshwater drilling fluids. Surface casing
will be set and cemented to surface from a depth of 1670'.
Porous/permeable soils: No, sandy clay soils.
Class I stream drainage: No Class I stream drainages in the area of review.
Mitigation:
X Lined reserve pit
X Adequate surface casing
Berms/dykes, re-routed drainage
bombaykes, is routed dramage

X Closed mud system X Off-site disposal of solids/liquids (in approved facility) Other: Comments: 1670' of steel surface casing cemented to surface is adequate to protect freshwater zones and cover the Fox Hills aquifer. Drill cuttings will be disposed of in the lined cuttings pit on the location. The cuttings pit will be backfilled after remaining fluids have evaporated. Oil based invert drilling fluids will be recycled. Completion fluids will be trucked to a commercial Class II disposal.
Soils/Vegetation/Land Use
Steam crossings: No, stream crossings, crossing only ephemeral drainages. High erosion potential: Yes, moderate cut, up to 17.3' and fill, up to 20', required. Loss of soil productivity: No, location will be restored after drilling, if nonproductive. If productive unused portion of drillsite will be reclaimed. Unusually large wellsite: Yes, large 400'X450' location size required for 2 wells Damage to improvements: No, slight. Conflict with existing land use/values: Slight, surface use grasslands. Mitigation Avoid improvements (topographic tolerance) Exception location requested X Stockpile topsoil Stream Crossing Permit (other agency review) X Reclaim unused part of wellsite if productive Special construction methods to enhance reclamation Other Comments: Access will use existing county road, #143. About a mile new and existing road, will be upgraded or constructed into this location from the existing county road #143. Drill cuttings will be disposed of in the lined cuttings pit. Oil based invert drilling fluids will be recycled. Completion fluids will be trucked to a commercial Class II disposal. Cuttings pit will be backfilled after remaining fluids have evaporated. Steep cut slope will need to be stabilized after well is drilled. No special concerns.
Health Hazards/Noise
(possible concerns) Proximity to public facilities/residences: Closest residences, none within 1 mile in any direction from this well location. Possibility of H2S: Slight chance of H2S (Mississippian Formations). Size of rig/length of drilling time: Triple drilling rig/short 30 to 40 days drilling time Mitigation: X_Proper BOP equipment Topographic sound barriers H2S contingency and/or evacuation plan Special equipment/procedures requirements Other: Comments: Adequate surface casing cemented to surface and operational BOP equipment will mitigate any issues.

Wildlife/recreation

(possible concerns)
Proximity to sensitive wildlife areas (DFWP identified): None identified.
Proximity to recreation sites: None identified.
Creation of new access to wildlife habitat: No
Conflict with game range/refuge management: None in the area.
Threatened or endangered Species: Species identified as threatened by the USFWS
are Pallid Sturgeon, Interior Lease Tern, Piping Plover and Whooping Crane. Species
listed as candidate species are the Greater Sage Grouse and Sprague's Pipit. NH
tracker website for this Township and Range lists only one (1) species of concern as the
Eastern Red Bat.
Mitigation:
Avoidance (topographic tolerance/exception)
Other agency review (DFWP, federal agencies, DSL)
Screening/fencing of pits, drillsite
Other:
Comments: Private surface lands. There may be species of concern that
maybe impacted by this wellsite. We ask the operator to consult with the surface owner
as to what he would like done, if a species of concern is discovered at this location. The
Board of Oil & Gas has no jurisdiction over private surface lands.
Historical/Cultural/Paleontological
(possible concerns)
Proximity to known sites: None identified.
Mitigation
avoidance (topographic tolerance, location exception)
other agency review (SHPO, DSL, federal agencies)
Other:
Comments: On private surface lands. There may be possible
historical/cultural/paleontological sites that maybe impacted by this wellsite. We ask the
operator to consult with the surface owner as to his desires to preserve these sites or
not, if they are found during construction of the wellsite. The Board of Oil & Gas has no
jurisdiction over private surface lands.
Social/Economic
(possible concerns)
Substantial effect on tax base
Create demand for new governmental services
Population increase or relocation
Comments: Wildcat well. No concerns
Remarks or Special Concerns for this site
·
Well is a single lateral horizontal Bakken Formation well.

Summary: Evaluation of Impacts and Cumulative effects

No long term impacts expected. Some short term surface impacts will occur.
I conclude that the approval of the subject Notice of Intent to Drill (does/ <u>does not</u>) constitute a major action of state government significantly affecting the quality of the human environment, and (does/ <u>does not</u>) require the preparation of an environmental impact statement.
Prepared by (BOGC): /s/Thomas Richmond(title:) Administrator
Date: November 19, 2013
Other Persons Contacted:
Montana Bureau of Mines and Geology, GWIC website (Name and Agency)
Richland County water wells
(subject discussed) November 19, 2013
(date)
US Fish and Wildlife, Region 6 website (Name and Agency) ENDANGERED, THREATENED, PROPOSED AND CANDIDATE SPECIES MONTANA COUNTIES, Richland County (subject discussed) November 19, 2013 date US Fish and Wildlife, Region 6 website
If location was inspected before permit approval: Inspection date: Inspector: Others present during inspection:
Others prosent during inspection.